

SB761
U7R6
no. 99-07

Forest Health Management

Biological Evaluation
R2-99-07

Phomopsis Blight at Bessey Nursery

March 1999



United States
Department of
Agriculture

Renewable Resources
Forest Health Management

Forest Service
Rocky Mountain Region
Denver, Colorado



The United States Department of Agriculture (USDA) prohibits discrimination on the basis of race, color, national origin, sex, religion, age, disability, political beliefs, and marital status. (Not all basis apply to all programs). Persons with disabilities who require alternative means for communication of program information (Braille, large print, audio tape, etc.) should contact the USDA Office of Communications at 202 / 720-2791.

To file a complaint, write the Secretary of Agriculture, U.S. Department of Agriculture, Washington, DC 20250, or call 800 / 245-6340 (Voice), or 202 / 720-1127 (TDD). USDA is an equal employment opportunity employer.

**Biological Evaluation
R2-99-07**

Phomopsis Blight at Bessey Nursery

March 1999

ROCKY MOUNTAIN RESEARCH STATION LIBRARY
FORT COLLINS CENTER
240 W PROSPECT RD
FORT COLLINS, CO 80526-2098

**Biological Evaluation
R2-99-07**

Phomopsis Blight at Bessey Nursery


March 1999

Prepared by:




For **Jeri Lyn Harris
Plant Pathologist
Rapid City Service Center**

Approved by:



For **Kurt K. Allen
Rapid City Service Center Leader
R2, Forest Health Management**

Approved by:



acting For **Robert D. Averill
Group Leader
R2, Forest Health Management**

Renewable Resources
USDA Forest Service
Rocky Mountain Region
740 Simms Street
Golden, CO 8040

Phomopsis Blight at Bessey Nursery

Abstract

Phomopsis blight disease, caused by the fungus *Phomopsis juniperovora*, destroyed several hundred-thousand eastern redcedar and Rocky Mountain juniper seedlings at Bessey Nursery during the 1998 growing season. The fungus spreads to new juniper foliage by dispersing spores through water splash during rain or irrigation. The fungus infects and kills new foliage and forms girdling cankers on small branches. The Spring seasons of 1997 and 1998 were cool, with above average rainfall and humidity during May through July. This weather promoted an outbreak of the blight at the nursery. Nursery workers applied fungicides and rogued infected trees from the beds. However, approximately 75% of the 1998 crop was lost to the disease. Forest Health Management identified the disease in seed beds and in surrounding shelterbelts. All of the fields planted with juniper and the surrounding shelterbelts were surveyed and infected specimens collected. Cultures of specimens on potato dextrose agar yielded 16% of the plates with the bright yellow fungal colonies characteristic of *P. juniperovora*. The fungus occurs throughout most of the nursery and the nearby forest lands at low, endemic levels, but climate conditions of 1998 promoted a dramatic increase in the disease. Recommendations are to use weekly systemic fungicide applications as soon as new growth appears and throughout the season. Monitor and remove infected seedlings and shelterbelt trees to help reduce the inoculum levels. Evaluate seed sources and outplanting results for possible genetic disease resistance.

Introduction

Phomopsis blight disease destroyed more than a quarter of a million eastern redcedar (*Juniperus virginiana*) and Rocky Mountain juniper (*J. scopulorum*) seedlings at Bessey Nursery during the 1998 growing season. Region 2 Forest Health Management - Rapid City Service Center (FHM) was asked to survey the Nursery's seedbeds and surrounding shelterbelts to confirm infection by Phomopsis blight and determine if the disease was present in the shelterbelts surrounding the nursery.

Ecology and Management of Phomopsis Blight

Phomopsis blight is a serious disease problem for nurseries that grow junipers in the Great Plains. The pathogenic fungus, *Phomopsis juniperovora*, spreads to new juniper foliage by dispersing spores through water splash during rainstorms or overhead irrigation. The spores penetrate new foliage and cause light yellow lesions on the new needles (Peterson 1973). The fungus then grows towards the stem of the branch and forms a canker. These cankers can girdle branches up to 1/3 inch in diameter and kill the distal foliage of the branch. The dead foliage turns reddish-brown with a definite demarcation line between the dead and live foliage. This demarcation line helps distinguish this symptom of Phomopsis blight from other drought or disease symptoms (Anderson et al. 1980).

Soon after the foliage dies it turns ash gray and produces spores from fruiting structures called pycnidia. Pycnidia appear as small black swellings embedded in the host tissue and produce two

type of spores, alpha and beta. Alpha spores are clear, non-distinct, spherical spores. Beta spores are slender, needle-like spores. Both spore types occur as tendrils or coils exuding from the pycnidia and are distributed by water movement. *P. juniperovora* spores are resilient and remain viable even after drying. As soon as climate and environmental conditions become right for spore development, the spores germinate and infect new host tissues. Optimal conditions for spore germination are at 100% humidity, for 7 hours, at 75° F (Peterson 1986).

The fungus infects and kills new foliage when it is still in its "light green" stage. Young trees are especially vulnerable to this fungus. A total crop loss is possible with first year seedlings and extensive crop loss may occur in second year seedlings. Sometimes the disease seems to be exacerbated late in the growing season as a late flush of new growth occurs to the seedlings (Otta et al. 1980).

Outplantings of infected trees, even slightly infected trees, are not promising (Peterson and Hodges 1989). The infected branches of the seedlings will reinfect the small tree again causing further damage and increase the likelihood of mortality (Hodges and Green 1961).

Mature trees in shelterbelts and landscape plantings may also become infected, but will probably only exhibit some dead branch tips since the fungus can only girdle small branches. Rarely will the disease kill mature trees but the dead branch tips may cause the plantings to look unsightly. These dead branch tips may also act as inoculum sources for the spread of the disease to younger trees (Peterson 1986; Anderson et. al. 1980).

Management for the disease consists of a combination of fungicide treatments, cultural practices, and using resistant seed sources (Peterson and Otta 1979). Systemic fungicides which translocate to new, vulnerable foliage are recommended. Benomyl and thiophanate fungicides have yielded good results when used every 7 - 10 days during the growing season (Otta 1973; Fiedler and Otta 1979; Otta et al. 1980). However, many of these fungicides are not currently listed for use with *P. juniperovora*.

Perhaps the best control method for nurseries is to remove infected seedlings as soon as the symptoms become evident. In the Great Plains region, seedlings should be closely monitored for this disease. Rogueing diseased seedlings when the foliage is dry reduces inoculum levels in the seedbeds and helps prevent healthy seedlings from being infected (Peterson 1986).

Reducing moisture on the foliage helps reduce outbreaks of the disease. Juniper seed beds should be located in well-drained soils to lower the available water to fungal spores. If shading frames are used for the seedlings, then the frames need to be removed in a timely manner to allow the foliage to dry before evenings (Anderson et. al. 1980).

Studies have shown that there can be disease resistance among different seed sources of juniper (Peterson 1984). Provenance plantings indicate that certain seed sources grow well in the Great Plains despite the presence of *P. juniperovora* in the area. Some of the most resistant seed sources for eastern redcedar have been found in central Nebraska (Schaefer 1995).

When large outbreaks of Phomopsis blight occur in a nursery, critical analysis of fungicide use, cultural practices, and the seed sources should be planned. This analysis will help nursery managers find better methods and materials to improve the nursery's production of juniper seedlings.

1998 Phomopsis blight outbreak at Bessey Nursery

The spring and early summers of 1997 and 1998 were cool and wet, with above average rainfall during the months of May through July. This type of weather has been shown to promote Phomopsis blight outbreaks in nurseries by providing a higher humidity which encourages spores to germinate (Schoeneweiss 1969).

Bessey Nursery managers started noticing problems with the fungus in May of 1998. They immediately started regular fungicide applications using Bravo® and Cleary 3336®. Nursery workers started roguing the infected seedlings from the beds when the trees were dry, disposing of the infected material into plastic garbage bags for removal from the field. It is estimated that the nursery lost approximately 250,000 seedlings in 1998.

Nursery managers were also suspicious about the mature trees in shelterbelts near the seed beds as inoculum sources. FHM was asked to review literature on the disease and identify the disease in shelterbelts to help determine if cedars should be removed. Dr. Glenn W. Peterson, a retired USDA Forest Service Research plant pathologist who worked extensively with Phomopsis blight, visited Bessey Nursery in October. Dr. Peterson helped assess the damage to the seed beds, clarified the identification of disease signs and symptoms, and offered possible solutions including fungicide and cultural control practices. His assistance was greatly appreciated.

With the amount of trees rogued from the beds and the customers' rejection of several trees suspected of the infection, the nursery lost approximately 75% of its 1998 crop due to Phomopsis blight.

Methods

Much of Bessey Nursery's fields are planted with eastern redcedar and Rocky Mountain junipers. Fields 1,2,4,5,6, and 7 (Figure 1) all contain beds of newly sown, one year old, or two year old seedlings. Collections of infected and dead seedlings were made from each field containing one and two year old seedlings. The collected seedlings were used for culturing and pathogen identification/confirmation.

All of the mature juniper within shelterbelts surrounding the nursery were closely examined for evidence of the disease. Surrounding forest trees within 50 feet of the nursery beds along the southern edge of the nursery were also examined. Dead branch tips that appeared to be infected with *P. juniperovora* were cut from every 10th juniper tree in the shelterbelts and forest edge for culturing.




Figure 1. Map of USDA Forest Service Bessey Nursery. Fields 1, 2, 4, 5, and 6 contain beds of eastern redcedar and Rocky Mountain juniper.

Culturing of suspect foliage was used for identification of the pathogen. Field specimens were brought indoors and rinsed with water to remove soil and other possible contaminants. The rinsing was also used to encourage sporulation from the pycnidia. Spores and infected host tissue were cultured on several potato dextrose agar petri plates. If cultures grew into bright yellow colonies, a characteristic of *P. juniperovora* culture (Peterson and Hodges 1989), this was accepted as confirmation of the fungus. Cultures were also magnified at 100X and examined for alpha and beta spores of *P. juniperovora*.

Results and Discussion

Of the culture work, 8 of 50 plates had bright yellow colonies and appeared to be *P. juniperovora*. The disease was found in Fields 1, 5 and 6. Phomopsis was also found in shelterbelts on the northern and western edges of Field 6 and 8 and in the shelterbelt on the eastern edge of field 3. An abundance of alpha spores were found, but no beta spores were observed. This was not surprising since Peterson 1973 reports few beta spores were found from field specimens.

Very little study has been done on how far spores from infected host tissue can travel during rain storms or overhead irrigation, so it is unknown how far away plantings of juniper should be to prevent infection to the nursery beds. Mature junipers from the surrounding shelterbelts probably ought to be removed prior to spring rainstorms and before new growth starts on the seedlings.

While the fungus was identified in these fields and shelterbelts, it probably occurs throughout most of the nursery and adjacent forest lands at low, endemic levels. Perhaps the cool, wet springs for two years promoted an outbreak of the disease in 1998. Early applications of fungicides as seedlings produce new, susceptible foliage should help prevent outbreaks. Possible good systemic fungicides, besides the two previously used by Bessey Nursery, are Bannor® and Chipco® (an epiodione). Close monitoring of seedbeds, and immediate rogueing of infected seedlings when they are dry will help reduce the spread of the fungus throughout the Nursery. Evaluations of seed sources and outplanting successes will provide useful information to nursery managers for possible genetic control measures for Phomopsis blight disease.

Recommendations

- Monitor disease spread in the nursery beds and follow with immediate rogueing of infected seedlings when the foliage is dry.
- Implement an active fungicide program as soon as new growth appears in the spring and continuing throughout the growing season at weekly intervals.
- Remove cedar from shelterbelts near the nursery beds. Consider removal of all mature junipers within 50 feet of the nursery beds.
- Evaluate seed source susceptibility to the disease and outplantings to identify superior seed sources for future disease resistance.

FHM will assist with as many of these recommendations as needed.

References

- Anderson, R.L.; Martin, M.B.; and Peterson, G.W. 1980. How to identify and control *Phomopsis* blight of junipers. USDA Forest Service, Southeastern Area, Forestry Bulletin SA-FB/P 25.
- Fiedler, D.J. and Otta, J.D. 1978. Control of *Phomopsis* blight of eastern redcedar with benomyl. In Proc. of American Phytopath. Soc. 4:126.
- Hodges, C.S. and Green H.J. 1961. Survival in the plantation of eastern redcedar seedlings infected with *Phomopsis* blight in the nursery. Plant Disease Reporter. 45(2):134-136.
- Otta, J.D. 1974. Benomyl and thiophanate methyl control *Phomopsis* blight of eastern redcedar in a nursery. Plant Disease Reporter. 58(5):476-477.
- Otta, J.D.; Fiedler, D.J.; and Lengkeek, V.H. Effect of benomyl of *Phomopsis juniperovora* infection of *Juniperus virginiana*. Phytopath. 70(1):46-50.
- Peterson, G.W. 1973. Infection of *Juniperus virginiana* and *J. scopulorum* by *Phomopsis juniperovora*. Phytopath. 63(2):246-251.
- Peterson, G.W. 1984. Resistance to *Phomopsis juniperovora* in geographic seed sources of *Juniperus virginiana*. In Proc. IUFRO Working Party Conference on Recent research on conifer needle diseases. Gulfport, Miss.,USA. Oct. 14-18, 1984. p. 65 - 69.
- Peterson, G.W. 1986. *Phomopsis* blight of junipers. In Diseases of trees in the Great Plains. Riffle J.W. and Peterson, G.W., Tech. Coord. USDA Forest Service, Rocky Mountain Forest and Range Experiment Station, Gen. Tech. Report RM-129. p. 112-113.
- Peterson, G.W. and Hodges, C.S. Jr. 1989. *Phomopsis* blight. In Forest Nursery Pests. USDA Forest Service, Ag. Handbook No. 680. p. 56-58.
- Peterson, G.W. and Otta, J.D. 1979. Controlling *Phomopsis* blight of junipers. Am. Nurseryman. 149(5):15,75,82.
- Schaefer, P.R. 1995. Ten-year results of an eastern redcedar and Rocky Mountain juniper provenance test in eastern South Dakota. North. J. Appl. For. 12(1):30-35.
- Schoeneweiss, D.F. 1969. Susceptibility of evergreen hosts to the juniper blight fungus, *Phomopsis juniperovora*, under epidemic conditions. J. Amer. Soc. Hort. Sci. 94(6):609-611.